


OCTOBER 2020

22 WELLS SAMPLED

22 WELLS - VINYL CHLORIDE NOT DETECTED

0 WELLS - VINYL CHLORIDE DETECTED AT OR BELOW HEALTH RISK LIMIT

0 WELLS - VINYL CHLORIDE DETECTED ABOVE HEALTH RISK LIMIT (0.2 µg/L)



LEGEND

- ND** VINYL CHLORIDE NOT DETECTED (DETECTION LIMIT = 0.086 µg/L)
- ND/ND** DUPLICATE SAMPLE RESULT
- NS** NOT SAMPLED (NO RESPONSE/DECLINED/WATER OFF)

- #RP** REPLACEMENT WELL INSTALLED BY RPs (PRAIRIE DU CHIEN AQUIFER) [OLD WELL ABANDONED]
- #RP-J** REPLACEMENT WELL INSTALLED BY RPs (EXTENDED INTO JORDAN AQUIFER AT HOMEOWNERS REQUEST/EXPENSE) [OLD WELL ABANDONED]
- #H-J** NEW WELL INSTALLED BY HOMEOWNER (JORDAN AQUIFER) [OLD WELL ABANDONED]
- *** CONVERTED RESIDENTIAL MONITORING WELL LOCATION



- CONNECTED TO MUNICIPAL WATER SUPPLY
- GEOGRAPHIC AREAS




figure 1
VINYL CHLORIDE CONCENTRATIONS
(OCTOBER 2020)
North Oaks, Minnesota